



(Edil)

D.1.12 SDS I Daily Visible Emissions Notations Per Each Daylight Shift (Stack SDS 04)

Inspector: Chemu S.				
Date of Inspection:				
Shift: 1st Shift or 2nd Shift) Time:	515 AM		
Unit and the second	Visual		Comments	
The state of the s	Inspection	and the second s		 The Carte Calculation of the Carte Carte
	<u>NORMAL</u>			
	or <u>ABNORMAL</u>			$\frac{1}{2} \frac{1}{2} \frac{1}$
V sible Emission From Shaker				
1	NORmail			
Visible Emission From Discharge				
Conveyor System	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.


(Stack SDS 04)

VISIBLE	EMISSION	NOTATION.
---------	-----------------	-----------

VISIBLE CITATION TO INTO THE					
Inspector: Vaul Larl					
Date of Inspection: 9-1-14	5				
Shift: 1st Shift or 2nd Shift	Time:	5:00 hm	1		
Unit (many many many many many many many many	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Com	ments	
Visible Emission From Shaker	nov				
Visible Emission From Discharge Conveyor System	nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015



(Stack SDS 04)

Inspector:					
MIKE PLL	ILLIPS				
Date of Inspection:	15				
Shift: 1st Shift or 2nd Shift	Time:	5 AM			
Unit	Visual	Tarana a di Para da Santa da S	Co	mments	e de la companya de
	Inspection		reserved at the property of th	to provide the second section of	and the second s
$P(x_0, x_0, x_1, \dots, x_n) = \frac{1}{2} \left(\frac{1}$	NORMAL		eran aller at the second of the second	en en skriver op de skriver op	and the state of t
(2.5,0.00) . The contrast of $(2.5,0.00)$ is the sum of $(2.5,0.00)$	or	Confidence of the Confidence			e de la companya de La companya de la co
	<u>ABNORMAL</u>				$ \frac{1}{2\pi} \left(\frac{1}{2\pi} \frac{\partial \mathcal{H}_{\mathcal{H}}}}}}}}}}$
Visible Emission From Shaker	- A - A	Monamore.			
	NORMAL				
Visible Emission From Discharge		control of			
Conveyor System	NORMAL				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			
Inspector: Hugh Hole	rnol		
Date of Inspection:			
Shift: (1st Shift) or 2nd Shif	t Time:	5:00 pm	
Unit Day of the second	Visual Inspection	The Council of County of Council of County of	Comments
	NORMAL		
	or <u>ABNORMAL</u>		
Visible Emission From Shaker	Norm		
Visible Emission From Discharge Convevor System	Norm		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

١	/ISIRI	E EN	115510	N NOT	ΓΔΤΙ	ONS
١	/ ISIDL	L LIV	HOOLU	יטעו עו	יווראו	UIVO

Inspector: Jaime Nova				
Date of Inspection: 9/3/15				
Shift: 1st Shift or 2nd Shif	t Time:	5 forman		
Unit Control of the C	Visual Inspection NORMAL or, ABNORMAL		. Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Mod			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE EMISSION NOTATIONS				
Inspector:	NO(01)	/		
Date of Inspection: 9 5 20) (
Shift: 1st-Shift or 2nd Shift	Time:	5:00pm		
	Visual Inspection <u>NORMAL</u> or ABNORMAL		omments	
Visible Emission From Shaker	Norm			
Visible Emission From Discharge Conveyor System	Norm			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.








Inspector:	Moland	- Contraction of the Contraction			
Date of Inspection:	36				
Shift: 1st Shift or 2nd Shift	t Time:	5.00pm			
	Visual Inspection <u>NORMAL</u> or ABNORMAL		Commen	nts	
Visible Emission From Shaker	Norm				
Visible Emission From Discharge Conveyor System	Norm				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.






TIGIBLE ETTILOSIOTI TO TATIOTA			 .	
Inspector: Jaime N Garcia				
Date of Inspection: 9/4//5				
Shift: 1st Shift or 2nd Shift	Time .	5A4		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comme!	
Visible Emission From Shaker	Nor	1.78(())))()())		
Visible Emission From Discharge Conveyor System	Noo	Santananana d		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015





VISIBLE EMISSION NOTATIONS

VISIOLE LIVISSICITION TO THE TOTAL					
inspector: Jame N Coa	Clica				
Date of Inspection: $9/5/5$					
Shift: 1st Shift or 2nd Shift	t Time:	5 AM			
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		an mortificación de la companya de	Comments.	
Visible Emission From Shaker	Nor	- Magnetic and the second and the se			
Visible Emission From Discharge Conveyor System	Nor	Angel College			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.


Revised 5/1/2015

(Stack SDS 04)

	,			_		_	_	n	Λ			٠.					_	` ¬	- 4		-,	$\overline{}$			_
١	/	IS	ı	к	1	F	H	i۱	/I	I١	١,	ы	() ľ	v	Ν	1)	Ľ	١	-1		ľ	V.	5

Inspector: Smelko					
Date of Inspection: Send 5	(5				
Shift: 1st Shift or 2nd Shift	Time:	5 AM			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comm	Contribute Colored and Contribute STAMES Contribute State	
Visible Emission From Shaker	nor	***Territorionales.			
Visible Emission From Discharge Conveyor System	nor	New Agreement of the Control of the			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS			_		
Inspector: Prome A Sa	neher				
Date of Inspection. 9/6/15)				
Shift: 2nd Shif	Time:	5:00 pm			
Unit)	Visual Inspection <u>NORMAL</u> or -ABNORMAL			omments	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Smello				
Date of Inspection:	5			
Shift: 1st Shift or 2nd Shif	t Time:	5 PM		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			
Visible Emission From Shaker	NOR	Prophasalove		
Visible Emission From Discharge Conveyor System	noR	NA _E ,		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE LIVISSION NOTATIONS					
Inspector: Freure A Sun	ruhez				
Date of Inspection: 9/4/15					
Shift: 1st Shift or 2nd Shift	t Time:	5:00, sul			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nor		_		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE EMISSION NOTATIONS	↑					
Inspector:	Jubrel:					
Date of Inspection:						
Shift: 1st Shift or 2nd Shif	t Time:	5:00pm				
esta se remain sur sunit esta en esta una	Visual	Service Country	Parada Estados (Comments 💎 💮		100
	Inspection		10.5			
The second secon	<u>NORMAL</u>	The second of th		#T-10 Section 1	is and the second	
	or,	and the second second	community of aging age	2674,6494		
the sale of the self-state of	<u>ABNORMAL</u>					- 1111 To 1111
Visible Emission From Shaker	MAN					
Visible Emission From Discharge						
Conveyor System	(1011)					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Jaime N Gar	Cia			
Date of Inspection: $9/8/15$				
Shift: 1st Shift or 2nd Shift	Time	5AM		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments :	
Visible Emission From Shaker	Non			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE LIVISSICITIONS				
Inspector:	Marga	The contract of the contract o		
Date of Inspection: 9815				
Shift: 1st Shift or 2nd Shift	Time:	5:capa	<u></u>	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comment:	
Visible Emission From Shaker	Varm			
Visible Emission From Discharge Conveyor System	Norm			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS					
Inspector: Jaime N G	alece				
Date of Inspection: 9/9/17					
Shift: 1st Shift or 2nd Shift	Time:	5AM			
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comn	No the agreement and a contract of the second and a second fills.	
Visible Emission From Shaker	Nex	e ^{ndermo} ce delemanosom			
Visible Emission From Discharge					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Conveyor System








VISIBLE EIVIISSICIT NO ITTIONS				
Inspector: Smell6				
Date of Inspection:	/)			
Shift: 1st Shift or 2nd Shift	Time:	SOOPM		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		omments	
Visible Emission From Shaker	no P			
Visible Emission From Discharge Conveyor System	no2			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS			_		
Inspector: C. Sauceco					
Date of Inspection:	·5				
Shift: 1st Shift or 2nd Shift	Time:	GAN			
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			comments	
Visible Emission From Shaker	NOL				
Visible Emission From Discharge					
Conveyor System	NOR	difference on the same of the	And the second s		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector: Smello				
Date of Inspection: Sept 10		·		
Shift: 1st Shift or 2nd Shift	Time:	SAM		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector: George A Some	chec			
Date of Inspection: 9/11/15				
Shift: 1st Shift or Ind Shift	Time:	5:00 pm		
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







Inspector: Smelk	0			
Date of Inspection: Sept 1	17			
Shift: 1st Shift or 2nd Shift	t Time:	SPM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Commenis	
Visible Emission From Shaker	nor	40106min.phys.co.		
Visible Emission From Discharge Conveyor System	nor	succession of the second of th		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

	rse A Sundrer		
Date of Inspection	on: 9/12/05		
Shift: 1st Shift	ft or 2nd Shift	Time: S. OU AV	
	l loit	Micros Commence of the Commenc	Com

Unit	Visual	Comments Comments
	Inspection	tal all the second of the seco
	<u>NORMAL</u>	
	r or	
	<u>ABNORMAL</u>	
Visible Emission From Shaker	Nor	
Visible Emission From Discharge	11	
Conveyor System	Nor	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector:	loland III	~		
Date of Inspection: 9 12 2015			_	
Shift: 1st Shift dr 2nd Shift	Time:	5:00		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Commen	
Visible Emission From Shaker	Normal			
Visible Emission From Discharge Conveyor System	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE EMISSION NOTATIONS			·		
Inspector: Jaime N Gora	îa .]		
Date of Inspection: 9/3/15]		
Shift: 1st Shift or 2nd Shift	Time:	5AL			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comme	ents	
Visible Emission From Shaker	NOR	Accomplished			
Visible Emission From Discharge Conveyor System	11/297				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS					
Inspector:	Nober	Quit			
Date of Inspection:	18/15				
Shift: 1st Shift or 2nd Shift	Time:	5:00pm			
Transfer with the Unit	Visual	The second second second	Comment	ts commente management	Company of Comments Confidence
10 10 10 10 10 10 10 10 10 10 10 10 10 1	Inspection			en e	
	<u>NORMAL</u>		and the state of the		Property of the Control of the Contr
	or .	April 1945 September 1945			A Company of the St.
	<u>ABNORMAL</u>	en eg distribuit de la company			
Visible Emission From Shaker	Normal				
Visible Emission From Discharge					
Conveyor System	Monred				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS

Inspector: Jaime Nocacia					
Date of Inspection: 9/14/15					
Shift: 1st Shift or 2nd Shift	Time:	5	1		
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL		Com	nments	
Visible Emission From Shaker	Nön	Constitution of the second sec			
Visible Emission From Discharge Conveyor System	Nor	and the second s			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015


(Stack SDS 04)

Inspector: Smello					
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	Time: <	5PM			
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comm	CONTRACTOR OF THE PROPERTY OF	
Visible Emission From Shaker	nor	and the second			
Visible Emission From Discharge Conveyor System	nor	Wagenio.			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

AISIBLE FIMISSION MOTATIONS			_		
Inspector: C. Sauceko					
Date of Inspection: $9-15-15$	_				
Shift: 1st Shift or 2nd Shift	Time:	515Au			
Unit 🗀	Visual	tropic families and community	Comments.	error error 4. These design (persons are se	3 (30 T) (23 - 13)
	Inspection			The second secon	
	<u>NORMAL</u>				
	or				
	<u>ABNORMAL</u>				
Visible Emission From Shaker	Λ. Α				
	NOR				
Visible Emission From Discharge				_	
Conveyor System	NOA	(b)			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



(Stack SDS 04)

			_		
Inspector: Smell CO					
Date of Inspection:	5,15				
Shift: (1st Shift) or \(\frac{1}{2}\) and Shift	Time: 🤄	5',00 pm			
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			omments	
Visible Emission From Shaker	NOW				
Visible Emission From Discharge Conveyor System	NOR				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

AISIBLE EMISSION NOTATIONS				
Inspector: Guerse A Sun	choc			
Date of Inspection: 9/16/15				
Shift: 1st Shift or 2nd Shift	Time:	5:00 Am		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.








VISIBLE EMISSION NOTATIONS			_		
Inspector: Chema	5,				
Date of Inspection: 9-1615p.w					
Shift: 1st Shift or 2nd Shift	Time:	Copm			
Supplied Record Unit and Control of the Control of	Visual: Inspection: NORMAL Or				
	ABNORMAL				
Visible Emission From Shaker	10em	-	<u> </u>		
Visible Emission From Discharge	1/5/2 00				
Convovor System	1 1/~)() 00				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

١	1	ıc	101			AIC C	ION	NO	ГΛТ		c
١	/	S	เซเ	_E	ΕI	ハンシ	IUIV.	IVU	IAI	IUN.	`

Inspector: Jame N Gaza	G.				
Date of Inspection: 9/19/15					
Shift: 1st Shift or 2nd Shif	t Time:	5			
Unit Unit	Visual		profit in the second section of	Comments	
	Inspection		unione Primario de Maria de Carlos de Primarios de Carlos de Carlo	the first term of the state of	
	NORMAL or		kaning to an early de- lated to the state of the state of the state of the state of		
	<u>ABNORMAL</u>			The product of the second seco	
Visible Emission From Shaker	Non				
Visible Emission From Discharge	6.0				
Conveyor System	Non				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS						
Inspector: Ruben	Moland					
Date of Inspection:	2015					
Shift: 1st Shift or 2nd Shift	Time:	5:00pm				
Unit	Visual	this can all the Manager transition	Con	nments 💮 🐃	Service Programme Consults	
	Inspection	er opriser i redakt ett militari	And the second s		ander still de still	4.400
Parameter and the second secon	<u>NORMAL</u>	10 mm (10 mm)				
	or				in the second	
	<u>ABNORMAL</u>					
Visible Emission From Shaker	Norm					
Visible Emission From Discharge	К {					
Conveyor System	NO(N)					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS	

Inspector: Jaime N Goac	- 1a			
Date of Inspection: 9/8/5	-	·		
Shift: 1st Shift or 2nd Shift	Time:	5Am		
Unit	Visual Inspection: <u>NORMAL</u> or <u>ABNORMAL</u>			
Visible Emission From Shaker	Nor	Account and account account		
Visible Emission From Discharge Conveyor System	Noa	-500 Million Commonweal and a		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS			_	
Inspector: Ruban N	blordan		-	
Date of Inspection:	18-15			
Shift: (st Shift) or 2nd Shift	Time:	50e		
rhida a salas di la Unith deplesario. La devició a la company de	Visual 1997 And Inspections	Series part of Confident Principles and Series Confidence in Confidence	Comme	
	<u>NORMAL</u>			
	or ABNORMAL			
Visible Emission From Shaker	Marmal			
Visible Emission From Discharge	102/00/01			
Conveyor System	H KANAAC I			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS

Inspector: Cheme	<u>.</u> 5				
Date of Inspection: $9 - 19 - 19 - 19 - 19 - 19 - 19 - 19 -$	5				
Shift: 1st Shift or 2nd Shift	Time:	5AM			
Pur la religious Uniteration de la company d	Visual	PARTICULAR DE LA COMPANION DE	Con The Street Constitution of the Street	nmentse (FAI)	militariya dine desim begirinde di disebilik beshir Papa kala di dikada salar bermana di dikada kala
residente de la companya de la comp La companya de la co	THE RESERVE OF THE PARTY OF THE				
	ABNORMAL	A Part of the Control			
Visible Emission From Shaker	NORmal)-		
Visible Emission From Discharge					
Conveyor System	Normal	Company of the last of the las	Designation of the second of t		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.








VISIBLE EMISSION NOTATIONS					
Inspector: Smell(0					
Date of Inspection:	19,15				
Shift: 1st Shift or 2nd Shift	t Time:	5,00			
	Visual 4 din Inspectiones			ommentsa Santananan	roomaanikullisen (1852), (saalikultisen) Historialikultisen (1852), (saalikultisen) Historia
	<u>NORMAL</u> IOF				
	<u>ABNORMAL</u>				
Visible Emission From Shaker	nop	gammagam	·		
Visible Emission From Discharge	000	7			
Conveyor System	1101/				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS

TIOTOLE EITHOUTOTT TO			_		
Inspector: Grerge Same	her				
Date of Inspection: 2/20/5					
Shift: 1st Shift or 2nd Shift	Time:	5:00 AM			
	Visual Section 1888 in Spection 1888 in Spection 1888 in Special Section 1888 in Section 1888		GOI THE STATE OF THE STATE OF	nments	
	or [<u>ABNORMAL</u>				
Visible Emission From Shaker	Nac				
Visible Emission From Discharge	11-				
Conveyor System	1 100				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS

			-		
Inspector: Smello					
Date of Inspection: Sept 20	,15				
Shift: 1st Shift or 2nd Shif	t Time:	5pm			
	Visual Inspection NORMAL OF ABNORMAL			nments e	
Visible Emission From Shaker	nor	Managa			
Visible Emission From Discharge	NOD	*Contants			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015







VISIBLE EIVIISSION	NOI	AHUI	12	 	 	
Inspector: (1	- /4	15cm	hee			
Date of Inspection:	1	1	_			

Shift: 1st Shift or 2nd Shift Time: 5:00 pm

	Visual 4 4 6 Inspections 2 5	Gomments Comments Com
	<u>NORMAL</u> or	
	<u>ABNORMAL</u>	
Visible Emission From Shaker	Nor	
Visible Emission From Discharge	1	
Conveyor System	Nor	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS					
Inspector: Chema &					
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	Time:	5pm			
hud meet leed tunit leed to the second to th	Visual de factions de la company de la compa	LOSS PORTON DE LA CALLE DE	Gommer Gommer	是是1975年,1975年,1975年,1975年,1975年,1975年,1975年,1975年,1975年,1975年,1975年,1975年,1975年,1975年,1975年,1975年,1975年,1975年	
	NORMAL FOR		Property of the Control of the Contr		
	ABNORMAL				
Visible Emission From Shaker	NOR				
Visible Emission From Discharge					
Conveyor System	NOR				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.








VISIBLE EMISSION NOTATIONS

Inspecto	or:						
Date of	Inspection:				-		
Shift:	1st Shift	or	2nd Shift	Time:	-		
	Üni			Visual I The State of		ren Paris de l'Alexandria. Paris de la company de l'Alexandria.	
VISIDIE	EIIIISSIUII FI	0111 31	iakei	Nomal			
1	Emission Fr or System	om Di	scharge	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.








VISIBLE EMISSION NOTATIONS

Inspector: Chemer	S				
Date of Inspection:	15				
Shift: 1st Shift or 2nd Shift	Time:	5 pm			
municipal production of the second se	Visual Inspection		danasi danasi danasi Got	nments .	entroperations of the forest and and the second of the sec
			er i i i i i i i i i i i i i i i i i i i		
	or <u>ABNORMAL</u>				
Visible Emission From Shaker	NOR				
Visible Emission From Discharge					
Conveyor System	NOR	· Canada Cara Cara Cara Cara Cara Cara Cara C			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Conveyor System







VISIBLE EMISSION NOTATIONS				
Inspector: Mizerby	ra			
Date of Inspection: 9 23	15-			
Shift: 1st Shift or 2nd Shift	t Time:	53		
	Visual Inspection		Con	
	<u>NORMAL</u> or			
	/ ABNORMAL			
Visible Emission From Shaker	Ď.		DOWN	
Visible Emission From Discharge				
Conveyor System			1 Jawil	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS					
Inspector: Smell	C				
Date of Inspection:	1,15				
Shift: 1st Shift or 2nd Shift	Time:	5 AM			
Representation of the Control of the	Visual Vi		practice presents of the control of	mments x 1 in 1990	
Visible Emission From Shaker	noR	Offitzerenic			
Visible Emission From Discharge Conveyor System	noe	w			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.






(Stack SDS 04)



Inspector: Colorse AS	unchez			
Date of Inspection: Vaulis				
Shift: 1st Shift or 2nd Shift	t Time:	S: Ouper		
Augustine entirolite anno anti-	Visual Westling		omments.	
	<u>NORMAL</u>			
	ior <u>ABNORMAL</u>			
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS

Inspector: Sme 16				
Date of Inspection: Sept 26	15			
Shift: 1st Shift or 2nd Shif	Time:	5AM		
	Visual Inspection NORMAL OI ABNORMAL	property and the second		
Visible Emission From Shaker	nor	Will demonstrate to the second		
Visible Emission From Discharge Conveyor System	nor	**************************************		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015







VISIBLE EMISSION NOTATIONS					
Inspector: Mizenb	219				
Date of Inspection: 0 7-5	5 715				
Shift: (1st Shift) or 2nd Shift	Time:	5 pm			
	inspection as a line		en erstjer vegetstel oppeking Barense begreven om districter begre Barense begreven om district	mments = 1	
Visible Emission From Shaker	NOR	The control of the co	The second secon	SCENEDIC TO STANDARD MAKE Y LINCOLD THE STANDARD	
Visible Emission From Discharge Conveyor System	NOR				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS				
Inspector: LAME N GAI	lCiG			
Date of Inspection: 9/16/15	·	·		
Shift: / 1st/Shift /or / 2nd Shift	: Time:	5 Am		
	Inspection. 2. 1 NORMAL	e Particular School Particular	Eomments ()	
	or <u>ABNORMAL</u>			
Visible Emission From Shaker	NOR	grant dell'international		
Visible Emission From Discharge Conveyor System	Non	*Police Communication (Contraction Contraction Contrac		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS			_		
Inspector: Paul Lank					
Date of Inspection:		·			
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm			
Province design of the constraint of the constra	Visual ward				
	NORMAL I I				
	OF ABNORMAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge	106				
Conveyor System	ן ויטיו				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.








VISIBLE EMISSION NOTATIONS			_		
Inspector: Rubin W	danctur				
Date of Inspection:	· ·				
Shift: 1st Shift or 2nd Shift	Time:	5:00am			
	Visual Inspection 1: 1:		Company of the Compan	mments :	
	<u>NORMAL</u> or <u>ABNORMAL</u>				
Visible Emission From Shaker	Namal				m.ne.a.caga
Visible Emission From Discharge Conveyor System	1 Sans				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.






VISIBLE EMISSION NOTATIONS			_		
Inspector: Chemas	aucedo				
Date of Inspection: Q-27-12					
Shift: (1st Shift) or 2nd Shift	Time:	Som			
the state of Unit and State of the State of	// // Visual // // // // // Inspection		Com	ments.	Park Stranger
(See Add an month of the add and the add and an add and an add and an add and an	<u>NORMAL</u> OI		programme de la companya de la comp La companya de la companya del la company		
	ABNORMAL				
Visible Emission From Shaker	NOR				
Visible Emission From Discharge				_	
Conveyor System	Noe				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS				
Inspector: Carge & Sunc	her			
Date of Inspection: 9/28/15				
Shift: 1st Shift or 2nd Shift	t Time: §	5:00 pm		
	Visual Inspection Normal or ABNORMAL	AND THE PROPERTY OF THE PARTY O	omments.	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor			22

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.









VISIBLE EMISSION NOTATIONS				
Inspector: Grosse Some	her			
Date of Inspection: 71/24/19	5	·		
Shift: 1st Shift or 2rd Shift	t Time:	5:00m		
	Visual distriction.		omments	
	<u>NORMAL</u> or			
	<u>ABNORMAL</u>			
Visible Emission From Shaker	Wor			
Visible Emission From Discharge	11			
Conveyor System	1000			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.








- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015





VISIBLE EMISSION NOTATIONS

Inspector:	and a second]	
Date of Inspection: 9/30/15	Q			
Shift: 1st Shift or 2nd Shift	Time:	5 Pm		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			
Visible Emission From Shaker	Nor	Vicasia del menuto por constitucione del constit	TO CONTROL (SHIPPON) AND THE SHIPPON AND THE S	
Visible Emission From Discharge Conveyor System	Nov	, n-visit Ciril Universit in Mela Messacoccus and materials (UVP Continue) (CIRIL) (CI	gonosis de gori de de la companio del companio de la companio del companio de la companio del companio del la companio del companio de la companio del companio d	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

T